

(406) 862-4636 www.celebraterentals.com

8oz POPCORN MACHINE OPERATING TIPS

We recommend you buy the pre-measured packages of Popcorn with oil.

- 1. Connect to proper grounded 120 volt supply.
- 2. Turn on LIGHT switch (located inside of cabinet). Light will come on in cabinet.
- 3. Turn on KETTLE/MOTOR switch and KETTLE/HEAT switch (located next to LIGHT switch) and wait about 4 to 6 minutes. <u>DO NOT</u> wait in between batches, only for initial startup.
- 4. Place 1/4 cup of oil in kettle. Immediately add 3/4 cup of raw popcorn plus desired amount seasoning salt. Or use pre-measured packages of popcorn with oil.
- 5. Allow corn to pop until popping ceases; then dump remaining popped corn from kettle by rotating handle clockwise 1/3 turn and pulling downward.
- 6. Repeat steps 4-6 for additional batches of corn.
- 7. Always turn KETTLE/MOTOR switch and KETTLE/HEAT switch OFF when machine is not in use.
- 8. NEVER USE WATER ON ANY PART OF THE KETTLE!
- 9. Only use soft cloth to wipe out cabinet. DO NOT USE ANY FORM OF CLEANERS ON ANY PART OF POPCORN MACHINE OR CABINET.