



EVENT & PARTY RENTAL

(406) 862-4636

www.celebraterentals.com

6oz POPCORN MACHINE OPERATING TIPS

We recommend you buy the pre-measured packages of Popcorn with oil.

1. **Connect to proper grounded 120 volt supply.**
2. **Turn on LIGHT switch (located inside of cabinet on top left). Light will come on in cabinet.**
3. **Turn on KETTLE switch (located next to LIGHT switch) and wait about 4 to 6 minutes. DO NOT wait in between batches, only for initial startup.**
4. **Place 1/6 to 1/4 cup of oil in kettle. Immediately add 1/2 cup of raw popcorn plus desired amount seasoning salt. Or use pre-measured packages of popcorn with oil.**
5. **Allow corn to pop until popping ceases; then dump remaining popped corn from kettle by rotating handle clockwise 1/3 turn and pulling downward.**
6. **Repeat steps 4-6 for additional batches of corn.**
7. **Always turn KETTLE switch OFF when machine is not in use.**
8. **NEVER USE WATER ON ANY PART OF THE KETTLE!**
9. **Only use soft cloth to wipe out cabinet. DO NOT USE ANY FORM OF CLEANERS ON ANY PART OF POPCORN MACHINE OR CABINET.**